

IS1001 Data-Over-Power (DOP) Board Firmware Update v1.2.4 Release Notes

October 17, 2018

- Fixed Serial port speed switch functionality (speed was being set to 115200 regardless of the switch position).

Updating Firmware Guidelines

The firmware update is done via BioTerm communication program. Please refer to IS1001-MTS User Manual for the procedure.

This firmware is only applicable to IS1001 DOP Boards with serial numbers 0045 and higher.

DOP Board that is configured for Serial communication and located at a PC side of a power cable cannot be updated via BioTerm.

For technical assistance please contact the Technical Services Department of Biomark at (208) 275-0011 or email customerservice@biomark.com.